

111796

COMMONWEALTH OF PENNSYLVANIA  
Dept. of Environmental Resources  
Southeast Regional Office  
555 North Lane  
Conshohocken PA 19428  
(215) 832-6199  
May 13, 1991

Mr. Jerry Curtin  
Remedial Project Officer  
U.S. EPA, Region III  
841 Chestnut Building  
Philadelphia PA 19107

Dear Jerry:

We have completed our review of the draft Remedial Investigation report for the Havertown PCP site, and have the following comments upon it.

Please include a geological map of the general area, and if applicable (i.e. the presence of faults etc.) a geological map of the immediate area.


The last sentence of page 5-4 states that "the potential exists that dissolved contaminant compounds could migrate beyond currently delineated plume boundaries", but two paragraphs later (page 5-5) the sentence "Steady state conditions would imply that the combined physical, chemical, and microbial processes acting on the contaminants prevent their further migration beyond the current plume boundaries." says the opposite. Please clarify.

The geological cross section (fig. 2-1) should have a reference to the well map (3-1). The well map should have a line on it which relates to the cross section.

On table 4-3 the word water is misspelled.

We are reviewing the Risk Assessment and Feasibility Study portions of the report, and will have our comments on them soon. If I can be of further service please call me at 832-6199.

Sincerely,



Dave Kennedy  
Project Officer

AR301260

cc. George Danyliw  
Woodrow Cole